

ELECTRON CAPTURE DETECTOR



ECD Cleaning or Refoiling Service

FSA is your one source for ECD (Electron Capture Detector) annual cleaning or anode refoiling. Service is available for all **Agilent / HP, Varian / Bruker, Scion, Shimadzu and Perkin Elmer GC detectors.**

During the cleaning process all gas seals are replaced. All internal and external contaminants are removed.

After servicing, all ECDs are verified leak free. Ion current is tested and verified to meet manufacturer specifications for use.

Pricing

- ECD Cleaning (All Models) \$1,050.00 plus shipping.
- Varian/Bruker/Scion ECD Refoiling \$2,000.00 plus shipping.

Prices subject to change, without notice

- Full documentation of post cleaning or refoiling ion current results provided.
- Competitive pricing and fast turn around time.

* Expedited service available - shipping extra*

Please call our Customer Service
Department at **800.795.6357.**

